

City of Detroit  
Department of Recreation Performance Audit  
Exhibit 1 – Belle Isle



This field had a hard surface with weeds growing on the infield.



This field (diamond 4) had a large divot leading into third base.

City of Detroit  
Department of Recreation Performance Audit  
Exhibit 1 – Belle Isle

**Shelters**

Overall Evaluation – Average Condition

- One of three shelters visited was freshly painted, clean and structurally sound.
- One of three shelters visited had some peeling paint and benches with cracks.
- One of three shelters visited was severely damaged structurally.



The outside of this shelter was well maintained.



The inside of the same shelter was freshly painted and well maintained.

City of Detroit  
Department of Recreation Performance Audit  
Exhibit 1 – Belle Isle



This shelter (number 7) shows severe damage and an attempt to restrict access.



The same shelter had severe roof damage and hanging wires.